

New Jersey Department of Transportation CONSTRUCTION ADVISORY

NUMBER: 32	Prelude to 2011 CPH Section VIII Subsection C	02/28/2018
CATEGORY: Work Zone Safety		

Section VIII "Work Zone Safety" of the 2011 CPH has yet to be published. The only procedural guidance for REs at this time on Work Zone Safety is the Pre 2011 CPH.

Section VIII Subsection C "Responsibilities of the Person Performing the Daily Traffic Control Plan Inspection" of the 2011 CPH is not being developed at this time as it is anticipated that changes to various requirements for various devices are forthcoming.

This Construction Advisory serves to direct the use of revised checklists for inspecting construction barrier curb and the various attenuators indicated in the Pre 2011 CPH Section VIII Subsection C. Attachments "B", "C", "D", "F" & "I" are replaced and can be found on the forms page as Form DC-189B, C, D, F & I at the following link:

[Forms page](#)

These checklists are to be used in the inspection of Truck Mounted Attenuators, Temporary Crash Cushion – Crushable Energy Absorbing System, Temporary Crash Cushion – Inertial Barrier System, Temporary Crash Cushion – Non-Redirective Energy Absorbing Terminal (N.E.A.T.) and Construction Barrier Curb

Snehal Patel PE, PMP
Director, Construction Services & Materials


